
Grease Interceptor Options Based on Application

March 2022





The flush-with floor automatic grease interceptor (shown on right) eliminates the need for costly service as well as odors.

www.highlandtank.com

GREASE INTERCEPTOR OPTIONS

Highland Tank is a leading manufacturer of grease interceptors. We offer interior and exterior models along with aboveground, buried, and atmospheric grease interceptors to best suit the application.

Our PGI series gravity type grease interceptors are structurally stronger than any of the other materials available. This type of grease interceptor is typically buried on the exterior of the building. However, in zero lot line applications, they have been installed in parking garages.

In this type of installation, Highland Tank is superior in offerings that include cylindrical designs with remote pump out to allow for easy maintenance of the interceptor. The interceptor can also be insulated for those applications where the interceptor is subjected to low temperatures. Integral lift stations can be added in applications that are unable to connect to sanitary sewer via gravity. These features in addition to others make Highland Tank the perfect fit for grease interceptor projects.

Highland Tank also offers a wide range of hydromechanical type grease interceptors. These range from point-of-use that are typically located at or near drainage fixtures to centralized grease interceptors designed to receive flow from multiple fixtures.

Our flush-with-floor automatic grease interceptors are popular for picking up indirect waste connections while eliminating the need of costly service and odors associated with the task.

When considering an automatic grease interceptor, factors to consider include ease of service or the inability to service traditional type hydromechanical grease interceptors. Another possibility of why hydromechanical grease interceptors are considered is the length of pipe to the exterior grease interceptor. Locating the grease interceptor closer to the fixtures may reduce buildup or blockages.

Call 814-893-5701 today or visit us at www.highlandtank.com for more information on grease interceptors.

Contact: Chas Tevis Email: ctevis@highlandtank.com